



## **Monitoring Station Data Sheet**

## **Ballyshingadaun, County Mayo**

## **Station Details**

Site Name	Ballyshingadaun	
County	Mayo	
X,Y (ITM)	519411, 757130	
Site ID	W53007	
Monitoring Type	GSI NON-ACTIVE	
URL		
Monitoring Period	23 Jun, 2017 - 11 Sep, 2019	
Current Logger Datum	18.57 mAOD	
Lowest Known Elevation	17.5 mAOD	








## **Peak Flood Observations**


Details of the highest levels recorded by Geological Survey Ireland or external organisations (if available)


	GSI data	External data
Max Depth (m)*	4.89	
Max Stage (mAOD)	22.39	
Max Volume (m³)	1,136,058	
Max Area (m²)	518,047	
Date Occurred	20 Dec, 2018	











Geological Survey Ireland is a division of the Department of the Environment, Climate and Communications